

Mine Inspection Reports

2nd Quarter 2018

Company		Mine
ERC Mining Indiana Group		GoldStar Mine
Inspection Date:	Thursday, April 12, 2018	
Areas Inspected:	Surface Areas of Underground - pit, highwall, roadways, openings, pumps, belts, shop, office, substation	
Findings / Law(s) Violated:	77.1110	
Corrective Actions Taken:	Hazards have been addressed with management and corrected	
Recommendation(s):	None noted	
Inspection Date:	Thursday, April 12, 2018	
Areas Inspected:	Underground Areas - primaries, secondaries, returns, unit, seals	
Findings / Law(s) Violated:	No Violations noted.	
Corrective Actions Taken:	None	
Recommendation(s):	None noted	
Inspection Date:	Thursday, April 26, 2018	
Areas Inspected:	Underground Areas - primaries, secondaries, returns, unit, seals	
Findings / Law(s) Violated:	No Violations noted.	
Corrective Actions Taken:	None	
Recommendation(s):	None noted	
Inspection Date:	Monday, June 25, 2018	
Areas Inspected:	Surface Areas of Underground - pit, highwall, roadways, openings, pumps, belts, shop, office, substation	
Findings / Law(s) Violated:	No Violations noted.	
Corrective Actions Taken:	None	
Recommendation(s):	None noted	
Company		Mine
Gibson County Coal		Gibson Mine (North)
Inspection Date:	Tuesday, April 17, 2018	
Areas Inspected:	Underground Areas (Portal 2) - primaries, secondaries, belts, unit	
Findings / Law(s) Violated:	75.202	
Corrective Actions Taken:	Hazards have been addressed with management and corrected	
Recommendation(s):	None noted	
Inspection Date:	Monday, April 23, 2018	
Areas Inspected:	Surface Facility Areas - plant, belts, tunnels, stackers, shop, warehouse, traffic flow, load-out	
Findings / Law(s) Violated:	No Violations noted.	

Corrective Actions Taken:	None
Recommendation(s):	None noted
Inspection Date:	Thursday, May 10, 2018
Areas Inspected:	Underground Areas (Portal 2) - primaries, secondaries, belts, unit
Findings / Law(s) Violated:	75.400
Corrective Actions Taken:	Hazards have been addressed with management and corrected
Recommendation(s):	None noted
Inspection Date:	Friday, May 11, 2018
Areas Inspected:	Surface of Underground Areas - roadways, pumps, shop, office, substation, fuel storage areas, parts yard, parts barn
Findings / Law(s) Violated:	No Violations noted.
Corrective Actions Taken:	None
Recommendation(s):	None noted
Inspection Date:	Monday, June 18, 2018
Areas Inspected:	Surface Facility Areas - plant, belts, tunnels, stackers, shop, warehouse, traffic flow, load-out
Findings / Law(s) Violated:	No Violations noted.
Corrective Actions Taken:	None
Recommendation(s):	None noted
Inspection Date:	Thursday, June 21, 2018
Areas Inspected:	Surface Areas of Underground (Portal 2) - roadways, pumps, shop, office, substation, fuel storage areas, parts yard, parts barn
Findings / Law(s) Violated:	No Violations noted.
Corrective Actions Taken:	None
Recommendation(s):	None noted

Company		Mine
Gibson County Coal		Gibson South Mine
Inspection Date:	Monday, April 16, 2018	
Areas Inspected:	Underground Areas - primaries, secondaries, belts, unit	
Findings / Law(s) Violated:	75.202(a); 75.1100-3	
Corrective Actions Taken:	Hazards have been addressed with management and corrected	
Recommendation(s):	None noted	
Inspection Date:	Tuesday, June 19, 2018	
Areas Inspected:	Surface Facility Areas - plant, belts, tunnels, stackers, shop, warehouse, traffic flow, load-out	
Findings / Law(s) Violated:	No Violations noted.	

Corrective Actions Taken:	None
Recommendation(s):	None noted

Company	Mine
----------------	-------------

Peabody Midwest Mining	Francisco Mine
-------------------------------	-----------------------

Inspection Date:	Wednesday, April 18, 2018
------------------	----------------------------------

Areas Inspected:	Underground Areas - unit, secondaries, primaries, belts
------------------	--

Findings / Law(s) Violated:	75.400; 75.1731(b)
-----------------------------	---------------------------

Corrective Actions Taken:	Hazards have been addressed with management and corrected
---------------------------	--

Recommendation(s):	None noted
--------------------	-------------------

Inspection Date:	Thursday, May 17, 2018
------------------	-------------------------------

Areas Inspected:	Surface Facility Areas - plant, belts, tunnels, stackers, shop, warehouse, traffic flow
------------------	--

Findings / Law(s) Violated:	77.400
-----------------------------	---------------

Corrective Actions Taken:	Hazards have been addressed with management and corrected
---------------------------	--

Recommendation(s):	None noted
--------------------	-------------------

Inspection Date:	Tuesday, June 19, 2018
------------------	-------------------------------

Areas Inspected:	Surface Facility Areas - plant, belts, tunnels, stackers, shop, warehouse, traffic flow
------------------	--

Findings / Law(s) Violated:	No Violations noted.
-----------------------------	-----------------------------

Corrective Actions Taken:	None
---------------------------	-------------

Recommendation(s):	None noted
--------------------	-------------------

Inspection Date:	Wednesday, June 20, 2018
------------------	---------------------------------

Areas Inspected:	Surface Areas of Underground - roadways, pumps, belts, shop, office, substation
------------------	--

Findings / Law(s) Violated:	No Violations noted.
-----------------------------	-----------------------------

Corrective Actions Taken:	None
---------------------------	-------------

Recommendation(s):	None noted
--------------------	-------------------

Company	Mine
----------------	-------------

Sunrise Coal	Carlisle Mine
---------------------	----------------------

Inspection Date:	Wednesday, April 11, 2018
------------------	----------------------------------

Areas Inspected:	Surface Areas of Underground - office, shop, warehouse, fuel storage areas, parts yard, belts
------------------	--

Findings / Law(s) Violated:	77.1110; 77.401(a)(2); 77.1102
-----------------------------	---------------------------------------

Corrective Actions Taken:	Hazards have been addressed with management and corrected
---------------------------	--

Recommendation(s):	None noted
--------------------	-------------------

Inspection Date:	Monday, April 30, 2018
------------------	-------------------------------

Areas Inspected:	Underground Areas - secondaries, unit, primaries, belts, seals
Findings / Law(s) Violated:	No Violations noted.
Corrective Actions Taken:	None
Recommendation(s):	None noted
Inspection Date:	Monday, May 14, 2018
Areas Inspected:	Surface Facility Areas - plant, belts, stackers, tunnels, load out, shop, warehouse, out buildings
Findings / Law(s) Violated:	No Violations noted.
Corrective Actions Taken:	None
Recommendation(s):	None noted
Inspection Date:	Thursday, June 28, 2018
Areas Inspected:	Surface Areas of Underground - office, shop, warehouse, fuel storage areas, parts yard, belts
Findings / Law(s) Violated:	No Violations noted.
Corrective Actions Taken:	None
Recommendation(s):	None noted

Company		Mine
Sunrise Coal		Oaktown Fuels #1 Mine
Inspection Date:	Thursday, April 5, 2018	
Areas Inspected:	Underground Areas (Portal ?) - secondaries, unit, primaries, belts	
Findings / Law(s) Violated:	75.202(a)	
Corrective Actions Taken:	Hazards have been addressed with management and corrected	
Recommendation(s):	None noted	
Inspection Date:	Tuesday, April 24, 2018	
Areas Inspected:	Underground Areas (Portal ?) - secondaries, unit, primaries, belts	
Findings / Law(s) Violated:	No Violations noted.	
Corrective Actions Taken:	None	
Recommendation(s):	None noted	
Inspection Date:	Friday, May 4, 2018	
Areas Inspected:	Surface Facility Areas - plant, shop, belts, tunnels, stackers, load out, surface machine shop, fuel storage areas, out buildings	
Findings / Law(s) Violated:	77.1110	
Corrective Actions Taken:	Hazards have been addressed with management and corrected	
Recommendation(s):	None noted	
Inspection Date:	Tuesday, May 15, 2018	

Areas Inspected:	Underground Areas (Portal 1) - secondaries, unit, primaries, belts
Findings / Law(s) Violated:	75.400
Corrective Actions Taken:	Hazards have been addressed with management and corrected
Recommendation(s):	None noted
Inspection Date:	Tuesday, June 26, 2018
Areas Inspected:	Underground Areas (Portal 2) - primaries, secondaries, belts, unit
Findings / Law(s) Violated:	No Violations noted.
Corrective Actions Taken:	None
Recommendation(s):	Keep chemical containers properly labeled or identified.

Company	Mine
----------------	-------------

Sunrise Coal		Oaktown Fuels #2 Mine
Inspection Date:	Wednesday, April 4, 2018	
Areas Inspected:	Surface Areas of Underground - office, shop, warehouse, fuel storage areas, parts yard, belts, stackers, tunnels	
Findings / Law(s) Violated:	No Violations noted.	
Corrective Actions Taken:	None	
Recommendation(s):	None noted	
Inspection Date:	Wednesday, May 2, 2018	
Areas Inspected:	Underground Areas - secondaries, unit, primaries, belts	
Findings / Law(s) Violated:	No Violations noted.	
Corrective Actions Taken:	None	
Recommendation(s):	None noted	
Inspection Date:	Wednesday, May 16, 2018	
Areas Inspected:	Underground Areas - secondaries, unit, primaries, belts	
Findings / Law(s) Violated:	75.1731(a)	
Corrective Actions Taken:	Hazards have been addressed with management and corrected	
Recommendation(s):	None noted	
Inspection Date:	Wednesday, June 27, 2018	
Areas Inspected:	Underground Areas - secondaries, unit, primaries, belts	
Findings / Law(s) Violated:	No Violations noted.	
Corrective Actions Taken:	None	
Recommendation(s):	None noted	

Company	Mine
----------------	-------------

Triad Mining		Freelandville West Mine
Inspection Date:	Thursday, April 12, 2018	
Areas Inspected:	Surface Areas of Underground - office, shop, warehouse, fuel storage areas, parts yard, pit, openings, substation, MCCs	
Findings / Law(s) Violated:	No Violations noted.	
Corrective Actions Taken:	None	
Recommendation(s):	None noted	
Inspection Date:	Friday, April 20, 2018	
Areas Inspected:	Surface Areas of Underground - office, shop, warehouse, fuel storage areas, parts yard, pit, openings, substation, MCCs	
Findings / Law(s) Violated:	No Violations noted.	
Corrective Actions Taken:	None	
Recommendation(s):	None noted	
Inspection Date:	Tuesday, May 1, 2018	
Areas Inspected:	Surface Areas of Underground - office, shop, warehouse, fuel storage areas, parts yard, pit, openings, substation, MCCs	
Findings / Law(s) Violated:	77.1109(c)(1); 77.502; 77.1103(a); 77.1109(e)(1); 77.1102; 77.208(d); 77.208(d); 77.809; 77.1103(d)	
Corrective Actions Taken:	Hazards have been addressed with management and corrected	
Recommendation(s):	None noted	
Inspection Date:	Friday, June 15, 2018	
Areas Inspected:	Surface Areas of Underground - office, shop, warehouse, fuel storage areas, parts yard, pit, openings, substation, MCCs	
Findings / Law(s) Violated:	No Violations noted.	
Corrective Actions Taken:	None	
Recommendation(s):	None noted	

Company	Mine
----------------	-------------

Triad Mining		Log Creek Mine
Inspection Date:	Friday, April 20, 2018	
Areas Inspected:	Surface Areas of Underground - office, shop, warehouse, fuel storage areas, parts yard, pit, openings, substation, MCCs	
Findings / Law(s) Violated:	No Violations noted.	
Corrective Actions Taken:	None	
Recommendation(s):	None noted	
Inspection Date:	Friday, April 20, 2018	
Areas Inspected:	Underground Areas - secondaries, unit, primaries, belts	
Findings / Law(s) Violated:	No Violations noted.	
Corrective Actions Taken:	None	

Recommendation(s):	None noted
--------------------	-------------------

Inspection Date:	Thursday, May 17, 2018
------------------	-------------------------------

Areas Inspected:	Surface Areas of Underground - office, shop, warehouse, fuel storage areas, parts yard, pit, openings, substation, MCCs
------------------	--

Findings / Law(s) Violated:	No Violations noted.
-----------------------------	-----------------------------

Corrective Actions Taken:	None
---------------------------	-------------

Recommendation(s):	None noted
--------------------	-------------------

Inspection Date:	Friday, June 22, 2018
------------------	------------------------------

Areas Inspected:	Surface Areas of Underground - office, shop, warehouse, fuel storage areas, parts yard, pit, openings, substation, MCCs
------------------	--

Findings / Law(s) Violated:	No Violations noted.
-----------------------------	-----------------------------

Corrective Actions Taken:	None
---------------------------	-------------

Recommendation(s):	None noted
--------------------	-------------------